

Product Security Advisory

2025T001

Several vulnerabilities in third party component Wibu Key

Affected Products

Product Name	Versions
All	All versions including and before v45

Vulnerability details

On November 13th 2025, several vulnerabilities were reported by Wibu Systems that may cause privilege scalation and denial of service. For further details check Wibu Systems provided documentation on the issue (here and here). **A fix is available** (see "Remediation" below).

Technical details:

- CVSS v3.1 base score: 8.8
- CVSS v3.1 vector: CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:C/C:H/I:H/A:H
- · Severity: high

Remediation

The remediation instructions below must be followed in all computers with Lantek software installed.

Recommended fixing approach. To fix the vulnerability **update the Wibu Systems driver to version 6.71 or later**. To do so, download the driver



from the Wibu Systems download page <u>here</u> and restart the computer afterwards.

Alternatively, install an updated version of Lantek software available in the following links (important, do not reuse installers you may have downloaded previously):

v45 SP1 METAL	METAL MTB SAPPHIRE	V2022 SP1 SHARP
v45 SP1 FACTORY	v43 SP2 METAL	V2021 SP1 METAL
v44 SP1 METAL	v43 SP2 SHARP	V2021 SP1 FACTORY
v44 SP1 FACTORY	V2022 SP1 METAL	V2021 SP1 SHARP
v44 SP1 SHARP	V2022 SP1 FACTORY	V2020 SP1 METAL
v43 SP2 FACTORY		

Additional notes

- The vulnerability, as stated by Wibu Systems, cannot be exploited remotely. A malicious user needs to have local access to the computer to be able to exploit it successfully.
- As best practice, we recommend always downloading the latest installers. If you downloaded one before and reuse it, it may not have the latest security updates.

Document revision history

Date	Author	Changes
November 18th,	Lantek Cybersecurity	Initial relase
2025	Team	

www.lantek.com • info@lantek.com • +34 945 771 700